CERCLA REMOVAL ACTION DAILY WORK ORDER

SITE NAME: Sweet Kleen Laundry

ORDER NO.: 20 SITE/SPILL NO.: UQ EPA REGION: II CONTRACTOR: WRS

MONITORS:

TO COMPLETION: 09/14/06

CONTRACT NO. EP-W-04-054

DATE: 06/12/06 - 06/23/06

SHIFT: As needed OSC: Kevin Matheis WORK ORDER # 39 RM: Scott Soden

NUMBER OF PERSONNEL AUTHORIZED

1 - Response Manager

1 - Equipment Operator 1- Foreman

EQUIPMENT AND EXPENDABLE MATERIALS AUTHORIZED

During the mobilization phase of the project, equipment to be utilized will be on an as needed basis, equipment will be added to this work order until site infrastructure is established.

Anticipated List

ITEM	QUANT.	ITEM	QUANT.
Computers	2	Office Trailers	0
4wd Truck	1	Equipment Trailer	0
Front end loader	1	Portable Toilet	0
MultiRae gas indicator	1	40kw Generator	0
Passenger Car	0	Fax Machine	0
Printers	1	Bobcat	0

I CERTIFY THAT THE ABOVE WORK IS ORDERED AND AUTHORIZED BY THE CONTRACTOR IN THE PERFORMANCE OF THE ABOVE CITED TASK ORDER

SIGNATURE OF	ON-SCENE	COORDINATO	3 1

Date 6906

I ACKNOWLEDGE RECEIPT OF THIS WORK ORDER.

SIGNATURE OF CONTRACTOR'S REPRESENTATIVE

Date 4 9 06

CERCLA REMOVAL ACTION DAILY WORK ORDER

SITE NAME: Sweet Kleen Laundry

ORDER NO.: 20 SITE/SPILL NO.: UQ EPA REGION: II

CONTRACTOR: WRS

MONITORS:

TO COMPLETION: 09/14/06

CONTRACT NO. EP-W-04-054

DATE: 06/12/06 - 06/23/06

SHIFT: As needed OSC: Kevin Matheis WORK ORDER #39

RM: Scott Soden

DESCRIPTION OF WORK TO BE PERFORMED

NOTE: All personnel work performed outside the site boundaries will be documented in an "OFF-SITE Hour Report" describing, in detail, activities performed and time charged in performance of these activities. Daily cost summary reports (1900-55) will also be submitted on a weekly basis unless provided daily, with the initiation of site activity. This item will be apply as long as the Task Order is open.

SPECIFIC TASKS

- 1. Prepare for shipment of hazardous waste soil per disposal facility protocol. Ship waste upon receipt of approvals and as scheduling permits.
- 2. Air monitor site during soil shipments.
- 3. Provide site security as needed during shipment process.
- 4. Prepare sampling plan for monitoring SVE system on-site. Provide draft sampling plan for OSC review by no later than COB June 23, 2006.
- 5. Implement sampling plan as instructed by OSC.
- 6. Other tasks as directed by the OSC.

CERCLA REMOVAL ACTION DAILY WORK ORDER

SITE NAME: Sweet Kleen Laundry ORDER NO.: 20 SITE/SPILL NO.: UQ EPA REGION: II CONTRACTOR: WRS MONITORS:	CONTRACT NO. EP-W-04-054 DATE: 06/12/06 - 06/23/06 SHIFT: As needed OSC: Kevin Matheis WORK ORDER # 39 RM: Scott Soden			
TO COMPLETION: 09/14/06				
AMENDMENTS				
I CERTIFY THAT THE ABOVE WORK IS ORDERED AND AUTHORIZED BY THE CONTRACTOR IN THE PERFORMANCE OF THE ABOVE CITED TASK ORDER Signatures only required on this page if amendments have occurred.				
SIGNATURE OF ON-SCENE COORDINATOR				
Date				
I ACKNOWLEDGE RECEIPT OF THIS WORK ORDER.				
SIGNATURE OF CONTRACTOR'S REPRESENTATIVE				
Date				
,	•			